


# MAIN REPAIR SHEET

SHEET NO. 1 OF 1

CITY		STREET OR BLOCK NO.		DATE	WORK ORDER NO.	CITY NO.	KEY NO.	GRID NO.	CASE NO.
Gas Tomia		900 Junior		9-13-74	347389	420	55	AN-25	18
PIPE SIZE	DEPTH	MAIN TO CURB	CONDITION	YEAR	INSTALLED	FOREMAN		SUPERVISOR	
34" CW	6"		good	1974		Thompson			
PRESSURE	TYPE OF REPAIR		SOURCE OF DISCOVERY		LOCATION OF LEAK		CAUSE OF LEAK		COATING
WC	MFG. Dresser Corp		<input type="checkbox"/> OUTSIDE CONSULTANT		<input checked="" type="checkbox"/> PIPE		<input type="checkbox"/> CORROSION		<input checked="" type="checkbox"/> COATED
600 PSI	STYLE 90P SIZE 34"		<input type="checkbox"/> COMPANY PERSONNEL		<input checked="" type="checkbox"/> VALVE		<input checked="" type="checkbox"/> DAMAGE BY OUTSIDE FORCE		<input type="checkbox"/> BARE
KIND	RENEW <input type="checkbox"/> MAIN-SERVICE		<input checked="" type="checkbox"/> DAMAGE BY OUTSIDE FORCE		<input type="checkbox"/> FITTING		<input type="checkbox"/> LEAKING BELL JOINT		<input type="checkbox"/> CAST IRON
MAIN	DATE OF DETECTION		<input type="checkbox"/> CUSTOMER		<input type="checkbox"/> DRIP		<input type="checkbox"/> CONSTRUCTION DEFECT		CATHODIC PROTECTION
SERVICE	9-13-74		<input type="checkbox"/> PUBLIC		<input type="checkbox"/> REGULATOR		<input type="checkbox"/> MATERIAL FAILURE		<input checked="" type="checkbox"/> PROTECTED
OTHER			<input type="checkbox"/> OTHER		<input type="checkbox"/> TAP CONNECTION		<input type="checkbox"/> OTHER		<input type="checkbox"/> UNPROTECTED
					<input type="checkbox"/> OTHER		GRADE OF LEAK		
							<input type="checkbox"/> I <input type="checkbox"/> II <input type="checkbox"/> III		

POSTED TO GIS BY VFM DATE 5/2/02

NOTE: FOR NEW CASES PLACE NEW UNDER CASE NUMBER.



REMARKS: Repaired service with Dresser Corp 1' CW pipe