

LOCATION 526 Belfast Dr. CITY SANTONIA
 BETWEEN Brightinton Ln. STREET & Colebrook Dr. STREET

| | SIZE | TYPE | LENGTH | INSTALLED | RETIRED | RENEWED |
|---------------------|------------|----------------|------------|----------------|---------|---------|
| MAIN TO BLDG. | <u>3/4</u> | <u>Plastic</u> | <u>109</u> | <u>5-28-96</u> | | |
| MAIN TO PROP. LINE | <u>3/4</u> | <u>Plastic</u> | <u>60</u> | | | |
| PROP. LINE TO BLDG. | <u>3/4</u> | <u>Plastic</u> | <u>49</u> | | | |

ENTERS: 526 BRANCHED INTO: 0

TAP SIZE: 3/8 PRESSURE 60 PSI _____ INCHES W.C. LOCATION: 140' Eaf. of Colebrook Dr.

PRESSURE TEST: @ 100 PSI FOR 1/4 HRS. BY RL

MAIN-SIZE 2" C.I. _____ BARE STEEL _____ COATED STEEL ✓ PLASTIC _____ YEAR INSTALLED 1976

DEPTH: 4 FT. 0 IN. LOCATION 30' N of C of Belfast Dr.

"A" P/S READING 1.1 TOTAL ANODES 1# 0 17# 0 L.R. # 272607

REMARKS:

| Test Station | | | ENG. DEPT. USE ONLY |
|---|----------|-------|----------------------|
| Reading & Location | Lead | Volts | <u>Riser plastic</u> |
| P/S Pipeline Lead - Red New Service | <u>S</u> | | |
| P/S Pipeline Lead - White Existing Main | <u>E</u> | | |

