

LOCATION 2415 Fairview Dr. CITY San Antonio
 BETWEEN Herron St. STREET & Green Meadows Dr. STREET

	SIZE"	TYPE	LENGTH	INSTALLED	RETIRED	RENEWED
MAIN TO BLDG	<u>5/8"</u>	<u>Plastic</u>	<u>90'</u>	<u>4/8/02</u>	<u>185' of Existing</u>	<u>3/4"</u>
MAIN TO PROP LINE	<u>5/8"</u>	<u>Plastic</u>	<u>14'</u>		<u>(4w) Pipe</u>	
PROP LINE TO BLDG	<u>5/8"</u>	<u>Plastic</u>	<u>76'</u>			

ENTERS 2415 BRANCHED INTO 0.

TAP SIZE 3/4 PRESSURE 40 PSI INCHES W/C LOCATION 21' w/ C of Green Meadows Dr.


PRESSURE TEST @ 100 PSI FOR 1/4 HRS BY RL

MAIN SIZE 2" C I BARE STEEL COATED STEEL PLASTIC ✓ YEAR INSTALLED 1991

DEPTH 3 FT 0 IN LOCATION 13' S of C of Fairview Dr.

"A" P/S READING Plastic N/A TOTAL ANODES 1# 0 17# 0 LR #

REMARKS



Test Station		
Reading & Location	Lead	Volts
P/S Pipeline Lead - Red New Service	S	
P/S Pipeline Lead White Existing Main	E	

Riser Plastic