


LOCATION 2569 Fairview Dr. CITY Stanton, IA
 BETWEEN Herron St. STREET & Lewallen St. STREET

	SIZE	TYPE	LENGTH	INSTALLED	RETIRED	RENEWED
MAIN TO BLDG	<u>5/8"</u>	<u>Plastic</u>	<u>225'</u>	<u>4-4-02</u>	<u>171' Existing</u>	<u>3/4"</u>
MAIN TO PROP LINE	<u>5/8"</u>	<u>Plastic</u>	<u>1.8'</u>		<u>City Service</u>	
PROP LINE TO BLDG	<u>5/8"</u>	<u>Plastic</u>	<u>207'</u>			

 ENTERS 2569 BRANCHED INTO 10
 TAP SIZE 3/4 PRESSURE 60 PSI INCHES W.C. LOCATION 300' E of C of Herron St.
 PRESSURE TEST @ 100 PSI FOR 4/4 HRS BY RL
 MAIN SIZE 2" C I BARE STEEL COATED STEEL PLASTIC ✓ YEAR INSTALLED 2002
 DEPTH 3 FT 6 IN LOCATION 16' S of C of Fairview Dr.
 "A" P/S READING Plastic N/A TOTAL ANODES 1# 0 17# 0 LR #
 REMARKS



Test Station		
Reading & Location	Lead	Volts
P/S Pipeline Lead Red New Service	S	<u>Riser</u>
P/S Pipeline Lead White Existing Main	E	<u>Plastic</u>