

LOCATION 3023 Hampton Brook Dr. CITY Crofton  
BETWEEN Erika Ln. STREET & Crofton Day School Rd. STREET

	SIZE	TYPE	LENGTH	INSTALLED	RETIRED	RENEWED
MAIN TO BLDG	5/8"	P	78'	4-9-02		
MAIN TO PROP LINE	5/8"	P	2'	"		
PROP LINE TO BLDG	5/8"	P	76'	"		

ENTERS 3023 BRANCHED INTO Ø

TAP SIZE 3/4" PRESSURE 60 PSI INCHES WC LOCATION 295' south


PRESSURE TEST @ 100 PSI FOR 1/4 HRS BY D. W. Brady  
center of Erika Ln.

MAIN-SIZE 2" C I        BARE STEEL        COATED STEEL        PLASTIC ✓ YEAR INSTALLED 1988

DEPTH 3' FT 0" IN LOCATION 21' West of center of Hampton Brook

"A" P/S READING N/A TOTAL ANODES 1# Ø 17# Ø LR # C0080744

REMARKS New Plastic Service



Test Station		
Reading & Location	Lead	Volts
P/S Pipeline Lead - Red New Service	S	plastic
P/S Pipeline Lead - White Existing Main	E	pipe